UNCLASSIFIED

AD 423377

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION ALEXANDRIA, VIRGINIA

UNCLASSIFIED

RESEARCH
ENGINEERING
PRODUCTION

GENERAL APPLIED SCIENCE LABORATORIES, INC.

MERRICK and STEWART AVENUES WESTBURY L I N Y

**PROPELLER BLADE
VIBRATION AND
STRESS ANALYSIS**

FINAL REPORT

TECHNICAL REPORT NO. 283

By Edward Lieberman

Prepared Under Contract No. Nonr-3072(00)X

Prepared for

Department of the Navy
David Taylor Model Basin
Washington 7, D. C.

Prepared by

General Applied Science Laboratories, Inc.
Merrick and Stewart Avenues
Westbury, L.I., New York

Approved by _Lee Arnold_
Lee Arnold
Vice President

June 1963

I.   SCOPE OF PROGRAMS

As indicated in References 2 and 3, the analyses by Dr. Frank Lane proved to be acceptable, using 45 degrees of freedom, only for flat plates, twisted bars , and, in general, for any geometrical configuration which was not characterized by severe twist, and large overhang of thin leading and trailing edges. Since many propeller blades do exhibit the geometrical configuration described above, it was suggested that the number of degrees of freedom be increased, to accommodate all propeller blade configurations.

Since the computer machine time increases roughly as the square of the number of degrees of freedom, it was decided to re-code the programs described in References 2 and 3, for the IBM 7090 computer, instead of for the IBM 704. Due to the size of the system, it was necessary to sub-divide the program into 4 CHAIN LINKS, to accommodate the storage requirements. During the course of field testing, it was found that single-precision arithmetic was inadequate in one section, and therefore it was necessary to utilize triple-precision arithmetic.

To illustrate the sharp contrast in scope, between the subject programs and their IBM 704 predecessors, up to 108 degrees of freedom may now be utilized, as compared with 45; 10 tapes versus 3, up to 146 mesh points versus 56 (integrating quadrature), and about 1 hour of IBM7090 computer time versus 40 minutes of IBM 704 time. As before, provision is made to restart the program with a minimum loss of machine time, in the event it must be removed from the computer prematurely due to lack of available time. In addition, the program may be easily restored in the event of a machine error.

No attempt will be made in this report to repeat Dr. Lane's analyses, which are described in Reference 1, and summarized in References 2 and 3. Only that information which pertains to these IBM 7090 programs will be included. The expanded sets of Rayleigh functions are listed in Appendix I.

PROPELLER BLADE VIBRATION ANALYSIS

The purpose of this IBM computer program is to generate the natural frequencies, mode shapes, and modal stress distributions for the ten lowest modes of vibration of propeller blades. This information, coupled with the fact that the eigenvectors are normalized with respect to the strain energy matrix, $(q^T V q = I)$, is sufficient to conduct any response analyses of propeller blades.

After accepting the input data which describe the blade geometry, the program generates a polynomial which fits, in the least squares sense, the camber distribution over the planform of the blade. The program then constructs a quadrature mesh which is later used to integrate the strain energy and kinetic energy, matrices over the blade planform. The two-matrix eigenvalue problem is reduced to a one matrix eigenvalue problem by factoring the strain energy matrix in triple-precision. This problem is then solved, and the resulting eigenvalues and eigenvectors are written as output. The relative stresses and displacements are calculated at mesh points over the blade planform, and are written as output.

This program will process sets of input data automatically. Core memory is salvaged on tape three times during the execution of the program which permits the program to be restarted with a minimum loss of time in the event of a machine failure.

This program has been written for a 32K (32,768 words) capacity
IBM 7090 computer, and utilizes ten tape units .

CHAIN LINK 1

The first two input cards, identification card and the first data card,
are read and immediately written on tape A3. The program then reads
and writes the remainder of the input data and calculates the thickness and
the local distance from the y^1, y^2 plane of each input point. The distribution
of camber, of the propeller blade, is then approximated with a least-squares
surface fit. The LeGendre-Gauss Quadrature weighting constants are stored
and the coordinates of the quadrature mesh points are calculated. The
program then dumps core memory on tape A5 and calls for CHAIN LINK 2.

CHAIN LINK 2

This section generates the potential (strain) energy, and the kinetic energy
matrices. At each quadrature mesh point, the program generates the funda-
mental forms, the Rayleigh functions, and the elements of the $T_{(i)}$ and $N_{(i)}$
matrices, as well as the local thickness. Utilizing these values, the local
contribution to the strain energy and kinetic energy matrices is formed and
multiplied by the local quadrature weight. All underflows are set to zero.
The program scans the quadrature mesh points, adding the weighted contri-
butions. The integrals are then modified to account for the root curvature.
After the integrals are formed, core memory is again salvaged on tape A5,
and CHAIN LINK 3 is called.

CHAIN LINK 3

The two-matrix eigenvalue problem is expressed as $Tq = \frac{1}{\lambda} Vq$. Using triple-precision arithmetic the strain energy matrix is factored, $V = M^T M$, where M is an upper triangular matrix. Then the system, $M^{-T} T M^{-1} Mq = \frac{1}{\lambda} Mq$, or $Fy = \frac{1}{\lambda} y$, where $F = M^{-T} T M^{-1}$ and $y = Mq$, is formed. This eigenvalue problem is solved using the SHARE routine, NYEVV, and the true eigenvectors calculated, $q = M^{-1} y$. These eigenvectors are normalized with respect to the strain energy matrix ($q^T Vq = I$). After saving core memory on tape A5, the program calls for CHAIN LINK 4.

CHAIN LINK 4

The ten lowest eigenvalues and their corresponding eigenvectors are stored in ascending order, and the mesh points at which the displacements and stresses will be evaluated, are calculated.

After writing the eigenvalues and eigenvectors for the lowest ten modes, and the mesh point coordinates on output tape A3, the program calculates the fundamental forms, Rayleigh functions, elements of the $T_{(i)}$ and $N_{(i)}$ matrices, the thickness at each mesh point, and then calculates displacements and stresses. Since the mesh is very dense, stresses are calculated at alternate mesh points while displacements are calculated at all mesh points, for all the ten modes of vibration. There are a total of 111 mesh points including the tip of the blade and 11 points along the blade root. The stresses and/or displacements at each mesh point are written on output tape A3. Control is returned to CHAIN LINK 1 to process the next run, if any. If no more data is available, the program exits.

The approximate computer production time for each set of input cards for an 8 x 9 quadrature mesh and 90 degrees of freedome is approximately 1 hour.

PROPELLER BLADE STATIC STRESS ANALYSIS

A. Program for Distributed Loads

The purpose of this IBM computer program is to generate the displacement and stress distribution of propeller blades for prescribed pressure-jump loadings. Provision is made for a "peaked" distributed loading with the singularity at the leading edge. The stresses are given directly; the displacements given must be divided by Young's Modulus.

After accepting the input data which describes the blade geometry, the program processes this data, and generates functions which accurately represent the blade configuration. A quadrature mesh is constructed which is then used to integrate the strain energy matrix over the blade planform. The program reads the pressure jump load data, and integrates this information over the blade planform to generate the forcing vector. To solve the resulting system of linear equations, the strain energy matrix is factored in triple-precision, and its inverse is computed. This approximate inverse is improved (if possible), and the solution vector is calculated and improved by use of iteration techniques. See Appendix II. The stresses and displacements at mesh points over the blade planform, are then calculated.

This program will process any sequence of inputs consisting of geometrical input data describing a particular blade, followed by any number of loading conditions for that blade, followed by another blade, etc. All inputs are written on the output tape, so that any error may be detected, and all

output listings uniquely identified. Core memory is salvaged on tape four times during the execution of the program which permits the program to be restarted with a minimum loss of time in the event of a machine failure.

This program has been written for a 32K (32,768 words) capacity IBM 7090 computer, and utilizes ten tape units.

The program is divided into four CHAIN LINKS, See pages 32 to 38 for detailed flow diagrams.

CHAIN LINK 1

The first two input cards, identification card and the first data card, are read and immediately written on tape A3. The program then reads and writes the remainder of the input data and calculates the thickness and the local distance from the y^1, y^2 plane of each input point. The distribution of camber of the propeller blade, is then approximated with a least-squares surface fit. The LeGendre-Gauss Quadrature weighting constants are stored and the coordinates of the quadrature mesh points are calculated. The program then dumps core memory on tape A5 and calls for CHAIN LINK 2.

CHAIN LINK 2

This section generates the potential (strain) energy matrix. At each quadrature mesh point, the program generates the fundamental forms, the Rayleigh functions, and the elements of the $T_{(i)}$ and $N_{(i)}$ matrices, as well as the local thickness. Utilizing these values, the local contribution to the strain energy matrix is formed and multiplied by the local quadrature weight.

All underflows are set to zero. The program scans the quadrature mesh

points, adding the weighted contributions. The integral is then modified to

account for the root curvature. After the integral is formed, core memory

is again saved on tape A5, and CHAIN LINK 3 is called.

CHAIN LINK 3

A code word is read and written which describes the type of

blade in the event the loading is "peaked" at the leading edge. The pressure-

jump distributed loading is then read and written. A forcing vector is formed

and integrated over the blade planform.

Core memory is saved on tape A5. The strain energy matrix is then

factored into triangular matrices in the form, $V = M^T M$, using triple-precision

arithmetic, and the matrix M^{-1} is generated. The inverse is then simply,

$V^{-1} = M^{-1} M^{-T}$, and is written on binary tape, B2, for subsequent loading

conditions, if desired. The solution vector is then calculated and improved by

iteration. All subsequent loading conditions use this inverse; only the new forcing

vector is computed. After saving core memory again on tape A5, the program

calls CHAIN LINK 4.

CHAIN LINK 4

The mesh points at which the displacements and stresses will be

evaluated, are calculated. After writing the solution vector and the mesh

points on the output tape, the program calculates the fundamental forms,

Rayleigh functions, elements of the $T_{(i)}$ and $N_{(i)}$ matrices, the thickness,

and then calculates displacements and stresses at each mesh point. These

values are written on the output tape. There are a total of 111 mesh points including the tip of the blade and 11 points along the blade root. If a new loading condition is to be read, CHAIN LINK 3 is called. If a new blade is to be analyzed, control is transferred to CHAIN LINK 1. Otherwise, the program exits.

The approximate computer production time for each complete set of input data cards for an 8 x 9 quadrature mesh and 90 degrees of freedom is approximately 1 hour. . For each subsequent set of pressure-jump inputs alone, the computer production time is approximately 1/2 hour.

II GEOMETRY

Figure 1 illustrates the propeller blade geometry and the coordinate systems utilized. The (y^1, y^2) coordinates form a two-dimensional Cartesian system in the transverse projection at the blade and serve as a Gaussian coordinate system in the blade middle-surface. The coordinate y^3 is normal to the local blade middle-surface, directed so that (y^1, y^2, y^3) form a right-hand system. It is to be noted that the camber and twist of the blade result in non-orthogonality of the (y^1, y^2) coordinate system. The third coordinate y^3 is, however, locally normal to y^1 and y^2.

The blade middle-surface is defined completely by describing its projected planform in the (y^1, y^2) plane and its local distance $f(y^1, y^2)$ from this plane as shown in Figure 1. The description of the thickness distribution serves to complete the geometric description of the blade.

The thickness at any point is found by linear interpolation of the input data.

III   INPUT FORMAT - VIBRATION

Card	Input Information
1	Identification
2	Poisson's Ratio, Blade Root Geometry, Size of System
3, 6, 9, ...	Section Properties
4, 7, 10,...	Offsets to Back Face Along Section
5, 8, 11,...	Offsets to Front Face Along Section
Final	Properties at Blade Tip

Refer to Figure 2.

Card No. 1:

Any identification statement of 72 characters or less will be accepted.
The statement may be punched in columns 2 - 72 of a card; the digit, "1"
should be punched in column 1 for output convenience.

Card No. 2:

Data	Columns	Format
ν	1-5	X.XXX
W_R	7-12	XX.XXX
W_L	14-19	XX.XXX
R_R	21-26	XX.XXX
R_L	28-33	XX.XXX
N	37-38	XX

The first word, ν, is Poisson's Ratio. The next 4 words, W_R, W_L, R_R, R_L are indicated in Figure 2. The number of degrees of freedom for each displacement component is N. Thus for 63 degrees of freedom, N is 21. If a full-scale problem is being run (108 degrees of freedom), N may be left blank.

Card No. 3:

Data	Columns	Format
% Radius	1-2	XX
Radius	4-9	XX.XXX or XXX.XX
Span	11-16	XX.XXX or XXX.XX
Pitch	18-24	$\pm$XX.XXX or $\pm$XXX.XX
Rake	26-32	$\pm$X.XXXX
Skew	34-40	$\pm$X.XXXX

Card No. 4:

Data	Columns	Format
A	1-6	$\pm$X.XXX or $\pm$XX.XX
E	7-12	
F	13-18	
G	19-24	
H	25-30	
J	31-36	
K	37-42	
L	43-48	
M	49-54	
N	55-60	
P	61-66	

Card No. 5:

Identical in format to Card No. 4.

Final Card

Data	Columns	Format
-	1-2	Must be blank
Radius	4-9	XX.XXX or XXX.XX
Thickness	11-16	XX.XXX
Pitch	18-24	XXX.XXX
Rake	26-32	±X.XXXX
Skew	34-40	±X.XXXX

The program can accept a maximum of 12 sections corresponding to a total of 40 input cards per set.

Cards 4 and 5 specify the thickness offsets along a section at equal chord increments, from leading-edge to trailing-edge. The offset of A is the offset near the leading edge, the offset of E is at one-tenth the chord distance from the leading edge, etc. The offset of P refers to the trailing-edge. See sketch below.

P N M L K J H G F E A

9 at 0.1 S = 0.9 S

S = Span

INPUT FORMAT - STRESS.

Card	Input Information
1	Identification
2	Poisson's Ratio, Blade Root Geometry
3, 6, 9, . . .	Section Properties
4, 7, 10, . . .	Offsets to Back Face Along Section
5, 8, 11, . . .	Offsets to Front Face Along Section
T-1	Properties of Blade Tip
T	Code Card
T+1, T+3, T+5, . . .	Pressure-jumps at points on sections corresponding respectively to those sections of input cards 3, 6, 9, . . . These points are from leading edge to 25% of chord.
T+2, T+4, T+6, . . .	Pressure-jumps at points on sections corresponding respectively to those sections of input cards 3, 6, 9, . . . These points are from 30% of chord to trailing edge.
C	Control Card

Next set of inputs, if any.

Refer to Figure 2.

Card No. 1:

Any identification statement of 71 characters or less will be accepted. The statement must be punched in columns 2-72 of a card. The digit, "1" should be punched in column 1 for convenience of output.

Card No. 2:

Data	Columns	Format
ν	1-5	X.XXX
W_R	7-12	XX.XXX
W_L	14-19	XX.XXX
R_R	21-26	XX.XXX
R_L	28-33	XX.XXX
N	37-38	XX

The first word, ν, is Poisson's Ratio. The next 4 words, W_R, W_L, R_R, R_L, are indicated in Figure 2. The number of degrees of freedom for each displacement component is N. Thus for 63 degrees of freedom, N is 21. If a full-scale problem is being run (108 degrees of freedom), N may be left blank.

Card No. 3:

Data	Columns	Format
% Radius	1-2	XX
Radius	4-9	XX.XXX or XXX.XX
Span	11-16	XX.XXX or XXX.XX
Pitch	18-24	$\pm$XX.XXX or $\pm$XXX.XX
Rake	26-32	$\pm$X.XXXX
Skew	34-40	$\pm$X.XXXX

Card No. 4:

Data	Columns	Format
A	1-6	±X.XXX or ± XX.XX
E	7-12	
F	13-18	
G	19-24	
H	25-30	
J	31-36	
K	37-42	
L	43-48	
M	49-54	
N	55-60	
P	61-66	

Card No. 5:

Identical in format to Card No. 4.

Card T-1:

Data	Columns	Format
-	1-2	Must be blank
Radius	4-9	XX.XXX or XXX.XX
Thickness	11-16	XX.XXX
Pitch	18-24	XXX.XXX
Rake	26-32	±X.XXXX
Skew	34-40	±X.XXXX

Card T:

Data	Column	Format
Code	1	X

Card T + 1:

Data	Columns	Format
P_0	1-7	XXX.XXX
$P_{1.25}$	9-15	
$P_{2.5}$	17-23	
$P_{5.0}$	25-31	
$P_{7.5}$	33-39	
P_{10}	41-47	
P_{15}	49-55	
P_{20}	57-63	
P_{25}	65-71	

Card T + 2:

Data	Columns	Format
P_{30}	1-7	XXX.XXX
P_{40}	9-15	
P_{50}	17-23	
P_{60}	25-31	
P_{70}	33-39	
P_{80}	41-47	
R_{90}	49-55	
P_{95}	57-63	
P_{100}	65-71	

Card C:

Data	Column	Format
Code	1	X

The program can accept a maximum of 12 sections corresponding to a total of 65 input cards per set.

Cards 4 and 5 specify the thickness offsets along a section at equal chord increments, from leading-edge to trailing-edge. The offset of A is the offset near the leading edge, the offset of E is at one-tenth the chord distance from the leading edge, etc. The offset of P refers to the trailing edge. See sketch below.

Card T specifies the type of peaked loading if any. The code is "1" for a "peaked" load and a super-cavitating blade, 0 for a "peaked" load and a fully wetted blade, and blank for any load which is not "peaked".

Cards T+1 and T+2 specify the complete pressure-jump loading acting on that section described on cards 3, 4 and 5. The subscripts of the p's are the percentages of chord, counting from leading edge to trailing edge. For example, p_0 is the pressure-jump loading acting at the leading edge of the section under

consideration; p_{20} acts at 20% of chord, or one-fifth the distance from the leading edge (this corresponds to F on the above sketch). Of course, p_{100} is the pressure-jump loading at the trailing edge (invariably, zero). Cards T+3 and T + 4 specify the pressure-jump loading on that section described on cards 6, 7, and 8; cards T + 5 and T + 6 pertain to cards 9, 10, and 11, etc. For a peaked loading, p_o, $p_{1.25}$ and $p_{2.5}$ must be zero.

The control card dictates the action of the program after a "run" has been completed. If no more inputs follow, the control card may be blank. If it is desired to conduct an additional analysis on the same blade using a different loading, the control card must have a "2" punched in column 1, and be followed immediately by cards specifying the loading, as described above (cards T through C). Should it be desired to conduct an analysis on another blade (no matter what the loading may be), a "1" must be punched in Column 1, followed by cards describing the new geometry and corresponding pressure-jump loading (cards 1, 2, 3..., C).

The formats indicated are representative. The decimal points may be shifted in either direction, so long as the input "word" is confined within the columns specified.

The program assumes that the tip of the blade is a point (span equal to zero) as is the case of a propeller blade. If the section at the blade tip has some span, such as the flat plates (Ref. 2 and 3) , it will be necessary to input two sections extremely close to the tip. In general, both sections should be within the outer 1% of the total blade span.

IV   OPERATING INSTRUCTIONS

These programs consist of rather large binary decks which should be loaded on tape using off-line peripheral equipment such as the IBM 1401, and mounted as input tape A2 on the main computer. The data cards are placed in the hopper of the on-line card reader as detailed below. .

The IB Monitor system must be used to run this program on the IBM 7090. The tape assignment cards (IOU tables) are included as part of the program deck. Tapes A1 through A5 and B1 through B5 are required for these programs. All output data is written on tape A3 which is to be printed using program control. Tape A5 is used as a salvage tape to store the entire contents of core periodically, so as to minimize loss of machine time. The restart procedure is described below. Tape A1 contains the IB Monitor Systems tape, tape A4 is used to store the chain links of the program, and tapes B-1 through B-5 are used as intermediate tapes by the Monitor system and as binary scratch tapes by the program itself. All tapes should be in the high density mode to conserve machine time.

Restart Procedure

A. In the event the program must be interrupted, due to some scheduling conflict or similar reason, dismount tape A5, and save. Print tape A3 and save this abridged output.

1. To restart the vibration program, re-mount tape A5 (but do not "ready" the tape unit), the systems tape, A1, and reload the program deck and data in the usual procedure, described above, as for a new run. As soon as EXECUTION commences, (on-line printer will indicate this word), depress

MANUAL key to MANUAL position, then "ready" tape A5. Depress the

console keys to read, 0 02000 0 00175, (transfer to location $(0175)_8$). Press

ENTER INSTRUCTION key. Depress MANUAL key to AUTOMATIC position.

Press START key.

Tape A5 will then be read, and the most recent condition of core,

prior to the last salvage, will be restored. The program will then

commence to execute, automatically.

2. To restart the stress program. , it is necessary that the

pressure-jump data be in core memory at the time of salvage. Thus, the

program must have initially executed either the 3rd or 4th dump on tape A5,

both taking place in the third CHAIN LINK, prior to manual termination of

run. If so, the procedure described above for the vibration program, will

apply,otherwise, the program must be run from the beginning. Note that

sequential runs are not possible when the program is restarted.

B. In the event of a machine failure, the restart procedure is some-

what simpler. Transfer via the console to location $(0175)_8$ as described

above, and the program will be restored. In this case, the restrictions for

the stress programs do not apply.

The only STOP anticipated, is when the accumulated round-off error causes

a number, whose square-root is required, to become negative. This will only

occur in LINK 3, and the program will exit automatically, with a statement

describing the cause.

This situation can only be remedied by re-running the program using lower

number of degrees of freedom. For a full discussion of this difficulty, refer

to section of conclusions.

Another STOP which may occur, is at location $(210)_8$. This is the result of being unable to write on tape A5 due (probably) to a "bad" tape. Replace this tape with another reel, and press START key. If this STOP persists, transfer via console to location $(213)_8$ to by-pass the dump. The program will not be affected unless a subsequent machine error occurs, in which case it will be necessary to restart the program from the beginning.

With the programs stored permanently on magnetic tape, the data cards will be read via the on-line card reader as follows:

1. Load the FORTRAN START card.

2. After IB Monitor begins to function (a few seconds), FEED out this START card.

3. Place data cards in card reader hopper and depress reader START key until READY light goes on.

4. Program will automatically read these cards. for END-OF-FILE convenience, place two blank cards at the end of the deck of data cards.

$\underline{\text{V}}$ BLADE VIBRATION ANALYSIS
FLOW DIAGRAM

START

LINK 1

READ
I. D. CARD

WRITE IDENTIFICATION

READ μ
W_R, W_L, P_R, P_L, N

SURFIT

$L = 0$

READ $\% R$,
R, SPAN, PITCH
RAKE, SKEW

$L = L + 1$

B

IS
$\% R = 0.0$

YES

NO

D

DOES
$L = 1$?

NO

YES

HUB RAD $= R$
$R_R = R_R - HUB \cdot RAD$
$R_L = R_L - HUB \cdot RAD$
$W_L = -W_L$

READ AND WRITE
OFFSETS ALONG SECTION

C

C

MODIFY LEADING
EDGE OF SECTION

CALCULATE POINTS
ALONG MEAN LINE
OF SECTION

CALCULATE SLOPE
OF MEAN LINE

CALCULATE EFFECTS
OF PITCH SKEW
RAKE & "WRAPPING"

CALCULATE LOCAL
DISTANCE OF EACH
POINT ON SECTION

LOCATE POINTS ON
BOUNDARY OF BLADE

B

D

TIP RAD = R
LOCATE POINT ON
TIP OF BLADE

FORM THE
(x^Tx) MATRIX

REARRANGE MATRIX IN
SAP MODE IN DOUBLE
PRECISION

USING NYDMI2,
INVERT MATRIX

REARRANGE INVERSE
IN FORTRAN MODE
IN SINGLE PRECISION

FORM THE
(x^Tx) MATRIX

MULTIPLY $(x^Tx)^{-1}(x^TY)$
& STORE COEFFICIENTS

CALCULATE THE
THICKNESS AT
EACH POINT

E

E

28

CALCULATE GAUSS
QUADRATURE WEIGHTS

CALCULATE COORDINATES
OF QUADRATURE
MESH POINTS

DUMP MEMORY
ON TAPE A5

LINK 2

RESET STORAGE AREAS
OF POTENTIAL & KINETIC
ENERGY MATRICES

SET PROGRAM TO SCAN
QUADRATURE MESH POINTS

COMPUTE FUNDAMENTAL
FORMS, RAYLEIGH FUNCTIONS
JACOBIAN ELEMENTS OF T_{ij}
& M_{ij} MATRICES & THICKNESS

IS VALUE
OF THICK
NEGATIVE
YES / NO

STOP

LOOP TO CALCULATE & ADD THE
SIX COMPONENTS OF THE
INTEGRAND OF THE FORM
$M_{ij} T M_{ij}$ FOR THE POTENTIAL
ENERGY MATRIX

MOVE TO NEXT
MESH POINT

F

REPEAT
PROCEDURE AT
CENTROIDS OF
ROOT AREAS TO
COMPLETE INTE-
GRATION OVER
BLADE PLANFORM

MULTIPLY INTEGRAND BY
THE QUADRATURE WEIGHT
& BY THE JACOBIAN & ADD
INTO STORAGE AREA

GENERATE THE ELEMENTS OF
THE SIX SUB-MATRICES WHICH
COMPRISE THE UPPER TRIANGLE
OF THE INTEGRAND OF THE
KINETIC ENERGY MATRIX

IS THE
QUADRATURE
COMPLETE
NO / YES

MULTIPLY INTEGRAND BY
THE QUADRATURE WEIGHT
& BY THE JACOBIAN & ADD
INTO STORAGE AREA

F

```
┌─────────────────────┐
│ DUMP MEMORY         │
│ ON TAPE A5          │
└─────────────────────┘
```

LINK 3

```
┌─────────────────────────────┐
│ REARRANGE STRAIN & KINETIC  │
│ ENERGY MATRICES FOR TWO     │
│ MATRIX EIGEN VALUE          │
│ ROUTINE                     │
└─────────────────────────────┘
```

```
┌─────────────────────────────┐
│ WRITE KINETIC ENERGY        │
│ MATRIX ON TAPE B3           │
└─────────────────────────────┘
```

```
┌─────────────────────────────┐
│ CONVERT STRAIN ENERGY       │
│ MATRIX TO  TRIPLE PRECISION │
│ AND WRITE ON TAPE           │
│ B5, ROW BY ROW              │
└─────────────────────────────┘
```

```
┌─────────────────────────────┐
│ BEGIN TO FACTOR STRAIN      │
│ ENERGY MATRIX. REWIND       │
│ TAPES B1, B2, & B5          │
│ TURN OFF ALL SENSE LIGHTS   │
└─────────────────────────────┘
```

```
┌─────────────────────────────┐
│ READ IN THE FIRST COLUMN    │
│ OF STRAIN ENERGY MATRIX FROM│
│ TAPE B5                     │
└─────────────────────────────┘
```

```
┌─────────────────┐
│ COMPUTE $d_1$   │
│ AND  $\gamma_1$ │
└─────────────────┘
```

```
┌─────────────────┐
│ $K = 0$         │
└─────────────────┘
```

```
┌───────────────────────────────────────────┐
│ SET UP LOOPING TO GENERATE THE REMAINING   │
│ N-1 COLUMS OF THE S UPPER-TRIANGULAR       │
│ MATRIX, AND THE N-1 ELEMENTS OF THE        │
│ DIAGONAL MATRIX, ALL IN TRIPLE PRECISION,  │
│ N IS DEGREES OF FREEDOM                    │
└───────────────────────────────────────────┘
```

G

G

K = K+1

READ IN THE C_K VECTOR
FROM TAPE B5

I = 0

H → I = I+1

DOES K = I
YES / NO

TEST SENSE LIGHT
OFF / ON

ROW = 0

SLN 1

READ I^{TH} RECORD
FROM TAPE B1

READ I^{TH} RECORD
FROM TAPE B2

THE ROW FORMED BY MULTIPLYING
THE I^{TH} ROW OF S BY D AND THEN
BY K-1 COLUMNS OF S_1^T HAS BEEN READ IN

AUGMENT EACH OF THE K-1 ELEMENTS
IN THIS ROW AND ALL THE K^{TH} ELEMENT

TEST SENSE LIGHT 1
OFF / ON

SLN 1

WRITE THE AUGMENTED
ROW ON TAPE B2

WRITE THE AUGMENTED
ROW ON TAPE B1

CALCULATE THE X_K VECTOR
EL. - ADD TO S MATRIX

DOES I = K
NO / YES

H ← → J

```
                              I
                              ↓
                        ┌──────────┐
                   OFF /   TEST     \ ON
                 ┌────┤   SENSE      ├────┐
                 │     \  LIGHT 1   /     │
                 ↓      └──────────┘      │
            ┌─────────┐                   │
            │  SLN 1  │                   │
            └─────────┘                   │
                 │                        │
                 └───────────┬────────────┘
                             ↓
                   ┌─────────────────────┐
                   │  REWIND  B1 & B2    │
                   └─────────────────────┘
                             ↓
                   ┌─────────────────────┐
                   │  CALCULATE D_{K+1}  │
                   └─────────────────────┘
                             ↓
                        ┌──────────┐
          NO           /   DOES     \           YES
       ┌──────────────┤   K = N-1    ├──────────────┐
       │               \            /               │
       ↓                └──────────┘                ↓
       G                                  ┌─────────────────────────────────┐
                                          │ ALL OPERATIONS WILL NOW BE IN    │
                                          │ SINGLE PRECISION.                 │
                                          │ TURN OFF SLT 1  REWIND  B5        │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ CONVERT THE S MATRIX TO SINGLE    │
                                          │ PRECISION AND WRITE ON B5 STORE   │
                                          │ √D' MATRIX, REWIND B5             │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ READ IN KINETIC ENERGY MATRIX     │
                                          │ FROM TAPE B3. REWIND B3           │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ READ IN S MATRIX FROM B5,         │
                                          │ CALCULATE AND STORE M⁻¹ MATRIX,   │
                                          │ THEN CALCULATE F MATRIX AND       │
                                          │ WRITE ON B3, ROW BY ROW           │
                                          │ REWIND B3, B5                     │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ WRITE M⁻¹ MATRIX ON B5,           │
                                          │ REWIND B5                         │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ READ IN F MATRIX FROM B3          │
                                          │ SYMETTRIZE AND STORE IN FAP MODE  │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ SOLVE EIGENVALUE PROBLEM          │
                                          └─────────────────────────────────┘
                                                      ↓
                                          ┌─────────────────────────────────┐
                                          │ FORM TRUE EIGENVECTORS BY         │
                                          │ PRE-MULTIPLYING BY M⁻¹, READ IN   │
                                          │ FROM TAPE B5, REWIND B5           │
                                          └─────────────────────────────────┘
                                                      ↓
                                                      J
```

READ IN S MATRIX FROM B5, CALCULATE AND STORE M^{-1} MATRIX, THEN CALCULATE F MATRIX AND WRITE ON B3, ROW BY ROW REWIND B3, B5

WRITE M^{-1} MATRIX ON B5, REWIND B5

FORM TRUE EIGENVECTORS BY PRE-MULTIPLYING BY M^{-1}, READ IN FROM TAPE B5, REWIND B5

J

```
┌─────────────────────┐
│   DUMP MEMORY       │
│     ON A5           │
└─────────────────────┘
```

LINK 4

```
┌──────────────────────────────┐
│ STORE THE TEN LOWEST EIGEN    │
│ VALUES IN ASCENDING           │
│ ORDER ALONG WITH THE          │
│ CORRESPONDING EIGEN VECTORS   │
└──────────────────────────────┘
```

```
┌──────────────────────────────┐
│ GENERATE THE MESH             │
│ POINTS AT WHICH DIS-          │
│ PLACEMENTS & STRESSES         │
│ WILL BE CALCULATED            │
└──────────────────────────────┘
```

```
┌──────────────────────────────┐
│ WRITE THE TEN EIGEN VALUES    │
│ & CORRESPONDING EIGEN VECTORS │
└──────────────────────────────┘
```

```
┌──────────────────────────────┐
│ WRITE THE COORDINATES         │
│ OF THE MESH POINTS            │
└──────────────────────────────┘
```

K

```
                              K

                    SET PROGRAM TO
                    LOOP OVER MESH
                    POINTS

                    GENERATE FUNDAMETAL
                    FORMS, RAYLEIGH FUNCTIONS
                    ELEMENTS OF T(i) & N(i)
                    MATRICES & THICKNESS
                    AT MESH POINT

                    IS THICK
                    NEGATIVE
                    ?
           NO                    YES

                              SET THICKNESS
                              EQUAL TO ZERO

                    SET PROGRAM TO
                    LOOP OVER MODES

                    CALCULATE
                    DISPLACEMENTS

                    ARE STRESSES
                    TO BE
                    GENERATED
                    AT THIS PT.
           NO              YES              STEP MODE

      WRITE                CALCULATE STRESSES
      DISPLACEMENTS        & STRESS GRADIENTS
      ON TAPE A3           AT MESH POINT

                          WRITE DISPLACEMENTS
                          & STRESSES ON TAPE A3

                    HAS PROGRAM
                    LOOPED THRU
                    ALL MODES
           YES                          NO

MOVE TO NEXT
MESH POINT

      HAS PROGRAM
      LOOPED OVER
      MESH POINTS
  NO               YES

            CALCULATE STRESSES AT ROOT

                    START
```

BLADE STATIC STRESS ANALYSIS
FLOW DIAGRAM

START

LINK 1

READ
I.D. CARD

WRITE IDENTIFICATION

READ μ
W_R, W_L, W_R, W_L

S.URFIT

$L = 0$

READ % R
R, SPAN, PITCH
RAKE, SKEW

$L = L + 1$

B

IS
% R = 0?

YES

NO

D

DOES
$L = 1$

NO

YES

HUB RAD = R
$R_R = R_R -$ HUB RAD
$R_L = R_L -$ HUB RAD
$W_L = W_L$

READ AND WRITE
OFFSETS ALONG SECTION

C

C

↓

MODIFY LEADING
EDGE OF SECTION

↓

CALCULATE POINTS
ALONG MEAN LINE
OF SECTION

↓

CALCULATE SLOPE
OF MEAN LINE

↓

CALCULATE EFFECTS
OF PITCH, SKEW
RAKE & "WRAPPING"

↓

CALCULATE LOCAL
DISTANCE OF EACH
POINT ON SECTION

↓

LOCATE POINTS ON
BOUNDARY OF BLADE

↓

B

D

↓

TIP RAD = R
LOCATE POINT ON
TIP OF BLADE

↓

FORM THE
(X^TX) MATRIX

↓

REARRANGE MATRIX IN
SAP MODE IN DOUBLE
PRECISION

↓

USING NYDMI2,
INVERT MATRIX

↓

REARRANGE INVERSE
IN FORTRAN MODE
IN SINGLE PRECISION

↓

FORM THE
(X^TY) MATRIX

↓

MULTIPLY $(X^TX)^{-1}(X^TY)$
AND STORE COEFFICIENTS

↓

CALCULATE THE
THICKNESS AT
EACH POINT

↓

E

E

CALCULATE GAUSS QUADRATURE WEIGHTS

CALCULATE COORDINATES OF QUADRATURE MESH POINTS

DUMP MEMORY ON TAPE A5

LINK 2

RESET STORAGE AREAS OF POTENTIAL & KINETIC ENERGY MATRICES

SET PROGRAM TO SCAN QUADRATURE MESH POINTS

COMPUTE FUNDAMENTAL FORMS, RAYLEIGH FUNCTIONS, JACOBIAN, ELEMENTS OF $T_{(i)}$ & $H_{(i)}$ MATRICES & THICKNESS

IS VALUE OF THICK NEGATIVE

YES   NO

STOP

LOOP TO CALCULATE & ADD THE SIX COMPONENTS OF THE INTEGRAND OF THE FORM $H_{(i)} T H_{(i)}$ FOR THE POTENTIAL ENERGY MATRIX

F

REPEAT PROCEDURE AT CENTROIDS OF ROOT AREAS TO COMPLETE INTEGRATION OVER BLADE PLANFORM

MOVE TO NEXT MESH POINT

MULTIPLY INTEGRAND BY THE QUADRATURE WEIGHT & BY THE JACOBIAN, & ADD INTO STORAGE AREA

NO   IS THE QUADRATURE COMPLETE   YES

35

F

```
┌──────────────────────────────────────┐
│   DUMP   MEMORY  ON  TAPE  A5          │
└──────────────────────────────────────┘

                                 LINK  3
┌──────────────────────────────────────┐
│  READ & WRITE PRESSURE-JUMP            │
│  DATA  ALONG  A  SECTION               │
└──────────────────────────────────────┘

┌──────────────────────────────────────┐
│  GENERATE  COORDINATES  OF             │
│  POINTS  USED  IN  CHORD-WISE          │
│  INTEGRATION                           │
└──────────────────────────────────────┘

┌──────────────────────────────────────┐
│  PERFORM  CHORD-WISE                   │
│  INTEGRATION  AND  STORE               │
└──────────────────────────────────────┘

        HAS  ALL  THE
        PRESSURE-JUMP
  YES   DATA  BEEN       NO
        READ ?

┌──────────────────────────────────────┐
│  CHOOSE  APPROPRIATE FORMULAS          │
│  FOR  SPAN-WISE  INTEGRATION           │
│  AND  EXECUTE                          │
└──────────────────────────────────────┘

┌──────────────────────────────────────┐
│   FORM  FORCING VECTOR                 │
└──────────────────────────────────────┘

┌──────────────────────────────────────┐
│   DUMP  MEMORY  ON  TAPE A5            │
└──────────────────────────────────────┘

                  G
```

G

IS THIS FIRST LOADING?

NO / YES

ARRANGE STRAIN ENERGY MATRIX FOR TRIPLE PRECISION FACTORIZATION

READ INVERSE FROM B2

FACTOR STRAIN ENERGY MATRIX (FOR DETAILED FLOW DIAGRAM SEE LINK 3 OF FLOW DIAGRAM OF VIBRATION PROGRAM) AND GENERATE THE M^{-1} MATRIX

CALCULATE THE INVERSE $V^{-1} = M^{-1} M^{-T}$

REWIND B2

CALCULATE THE SOLUTION VECTOR

WRITE INVERSE ON B2

DUMP MEMORY ON TAPE A5

ITERATE TO IMPROVE THE SOLUTION VECTOR

I

I

$$L = 2$$
$$n = 1$$

IMPRV

CALCULATE THE ERROR MATRIX C_1
COMPUTE THE NORM $\|C_1\|$
$$VV_n^{-1} = I + C_n$$

CALCULATE $V_{n+1}^{-1} = V_n^{-1}(I - C_n + C_n^2 - C_n^3 + C_n^4 - C_n^5)$

$$n = n + 1$$

CALCULATE $C_n \cdot VV_n^{-1} = I + C_n$ AND
THE NORM, $\|C_n\|$

IS
$$\|C_n\| \leq \|C_{n-1}\|$$
YES   NO

$$L = L + 1$$

IMPEV

CALCULATE $q_1 = V_n^{-1} P$

$$i = 1$$

CALCULATE $V q_i = p + f_i$
THE ERROR IN q_i IS $\Delta q_i = V_n^{-1} f_i$

$$i = i + 1$$

$$q_i = q_{i-1} + \Delta q_{i-1}$$

IS EACH TERM
$$\Delta q_{i-1} < 0.0001$$
YES   NO

J

IS $\|q_i\|$
$$< \|q_{i-1}\|$$
NO   YES

$$L = L + 1$$

SIDELIAN ITERATION TO IMPROVE
q VECTOR USING $2 \cdot N3/(L+1)$
CYCLES OF $N3/(L+1)$ ITERATIONS
EACH ($N3$ IS SIZE OF SYSTEM)

J   LINK 4

SET PROGRAM TO
LOOP OVER MESH
POINTS

GENERATE FUNDAMENTAL FORMS
RAYLEIGH FUNCTIONS, ELEMENTS
OF $T_{(i)}$ & $N_{(i)}$ MATRICES &
THICKNESS AT MESH POINT

IS THICK
NEGATIVE
?
  NO   YES

SET THICKNESS
EQUAL TO ZERO

CALCULATE
DISPLACEMENTS

CALCULATE STRESSES
& STRESS GRADIENTS
AT MESH POINT

WRITE DISPLACEMENTS
& STRESSES ON TAPE A3

MOVE TO NEXT
MESH POINT

HAS PROGRAM
LOOPED THRU
ALL POINTS
NO   YES

CALCULATE STRESSES & DISPLACEMENTS
AT TIP POINT AND ALONG BLADE ROOT

READ CODE CARD

CODE IS	0	1	2

WRITE STATEMENT ON ON-LINE PRINTER

LINK 3 START

EXIT

VI.   COMPARISON OF RESULTS

Vibration Program:

The table below lists the experimental frequencies obtained from a model of the DD 828 propeller blade (Reference 4), and computed frequencies utilizing 45 degrees of freedom, which was the limit for the previous IBM 704 program, and 90 degrees of freedom.   An 8 x 9 quadrature integrating mesh was used for both computer runs.   A density of 0.31 lbs./cu. in. and a modulus of elasticity of $15 \cdot 10^6$ psi, were assumed. The scale factor between the model and the actual blade is 10.125.

The comparison is made on the basis of similar mode shapes. Note that the mode shape for the third experimental mode corresponds with that obtained by the computer for its second mode, and vise-versa.

MODEL

Mode	Computed		Experimental
	45	90	
1	573	480	446
2	949	800	981 (3)
3	1140	1017	945 (2)
4	1392	1139	1220
5	1496	1392	--
6	2005	1610	1425
7	2441	1845	1640
8	2577	2111	1890
9	2753	2210 (84)	2097
10	3062	2450 (84)	2350

The tables on the following pages indicate the asymptotic behavior of the eigenvalues (and natural frequencies), as the number of degrees of freedom prescribed, is increased. This behavior is graphically illustrated on page 43.

The mode shapes are shown on pages 44 to 53 . The solid lines are drawn from data generated by the program; the broken lines were those detected experimentally. It became increasingly difficult for the experimenter to obtain the mode shapes as the frequency increased; therefore, no comparison is attempted beyond mode number 7.

COMPARISON OF EIGENVALUES

MODE	DEGREES OF FREEDOM					
	30	45	63	75	84	90
1	$0.125 \cdot 10^{-4}$	$0.915 \cdot 10^{-5}$	$0.776 \cdot 10^{-5}$	$0.674 \cdot 10^{-5}$	$0.645 \cdot 10^{-5}$	$0.641 \cdot 10^{-5}$
2	$0.348 \cdot 10^{-4}$	$0.251 \cdot 10^{-4}$	$0.208 \cdot 10^{-4}$	$0.193 \cdot 10^{-4}$	$0.182 \cdot 10^{-4}$	$0.178 \cdot 10^{-4}$
3	$0.455 \cdot 10^{-4}$	$0.362 \cdot 10^{-4}$	$0.325 \cdot 10^{-4}$	$0.306 \cdot 10^{-4}$	$0.302 \cdot 10^{-4}$	$0.288 \cdot 10^{-4}$
4	$0.947 \cdot 10^{-4}$	$0.540 \cdot 10^{-4}$	$0.413 \cdot 10^{-4}$	$0.391 \cdot 10^{-4}$	$0.387 \cdot 10^{-4}$	$0.361 \cdot 10^{-4}$
5	$0.975 \cdot 10^{-4}$	$0.623 \cdot 10^{-4}$	$0.599 \cdot 10^{-4}$	$0.546 \cdot 10^{-4}$	$0.545 \cdot 10^{-4}$	$0.540 \cdot 10^{-4}$
6	$0.175 \cdot 10^{-3}$	$0.112 \cdot 10^{-3}$	$0.814 \cdot 10^{-4}$	$0.788 \cdot 10^{-4}$	$0.759 \cdot 10^{-4}$	$0.722 \cdot 10^{-4}$
7	$0.211 \cdot 10^{-3}$	$0.166 \cdot 10^{-3}$	$0.118 \cdot 10^{-3}$	$0.103 \cdot 10^{-3}$	$0.953 \cdot 10^{-4}$	$0.948 \cdot 10^{-4}$
8	$0.316 \cdot 10^{-3}$	$0.185 \cdot 10^{-3}$	$0.145 \cdot 10^{-3}$	$0.130 \cdot 10^{-3}$	$0.130 \cdot 10^{-3}$	$0.124 \cdot 10^{-3}$
9	$0.434 \cdot 10^{-3}$	$0.211 \cdot 10^{-3}$	$0.154 \cdot 10^{-3}$	$0.138 \cdot 10^{-3}$	$0.136 \cdot 10^{-3}$	
10	$0.495 \cdot 10^{-3}$	$0.261 \cdot 10^{-3}$	$0.203 \cdot 10^{-3}$	$0.179 \cdot 10^{-3}$	$0.167 \cdot 10^{-3}$	

COMPARISON OF FREQUENCIES FOR VARYING DEGREES OF FREEDOM

MODE	DEGREES OF FREEDOM					
	30	45	63	75	84	90
1	66.1	56.6	52.1	48.6	47.5	47.4
2	110	93.7	85.3	82.2	79.4	78.9
3	126	113	107	104	103	100
4	182	137	120	117	116	112
5	185	148	145	138	138	137
6	248	198	169	166	163	159
7	272	241	203	190	183	182
8	333	254	225	213	211	208
9	340	272	232	220	218	
10	416	302	267	250	242	

Plot of Eigenvalues versus Degrees of Freedom

Modes

10

9

8

7

6

5

4

3

2

1

0.5×10^{-3}

0.1×10^{-3}

0.5×10^{-4}

0.1×10^{-4}

0.5×10^{-5}

0.1×10^{-5}

Eigenvalues

30   45   63   75   84   90

Degrees of Freedom

PROPELLER BLADE

MODE NO. 1

PROPELLER BLADE

MODE NO. 2

PROPELLER BLADE.

MODE NO. 3

MODE NO. 4

PROPELLER BLADE

MODE NO. 5

MODE NO. 6

PROPELLER BLADE

MODE NO. 7

PROPELLER BLADE

MODE NO. 8

MODE NO. 9

PROPELLER BLADE

MODE NO. 10

Stress Program

The stress program is subject to the same round-off error problems associated with the vibration program. Indeed, the triple-precision technique used to factor the strain energy matrix, is identical for the two programs. Thus the same restrictions on maximum size of the system that apply for the vibration program, also apply for the stress program.

A parallel series of test runs was conducted on the DD828 propeller blade, using a "peaked" pressure-jump loading. Two runs were conducted at 84 degrees of freedom, one using twice as many iterations to improve the solution vector, as is normally used. The results of the two runs were practically identical, indicating that an adequate number of iterations are being used and that the solution of the system of linear equations, is accurate. Another series of test runs was conducted on a stainless steel propeller, loaded with a uniform pressure distribution.

Discussion

The results of the first series of runs were conducted using 45, 63 and 84 degrees of freedom, and are indicated graphically on the following pages. In addition, detailed displacement and stress distributions are plotted over the blade planform for the run utilizing 84 degrees of freedom.

It is worth noting that as the size of the system grows, the free boundary conditions are satisfied with increasing accuracy. The graph on page 57 clearly indicates this trend, with the span-wise stress (σ^{11}) virtually vanishing at the blade tip for the run utilizing 84 degrees of freedom. In addition, this trend is also true for the chord-wise stress (σ^{22}), indicated on page 56.

The final results obtained by using 84 degrees of freedom for the stainless steel propeller, are graphically shown on pages 58 to 67 .

Displacement (U(3)) vs. $y^{(1)}$ at mid-chord
for 3 degrees of freedom

$U(3) \times 10^{-6}$

$\gamma^{(1)}$

84°

63°

45°

24

20

16

12

8

4

0   10   20   30   40   50   60   70   80

Chord-wise stress (σ^{zz}) vs. y (x) at 6/10 span for 3 degrees of freedom – front and back faces

Span-wise Stress (σ'') vs. $y^{(1)}$ at mid-chord for 3 degrees of freedom - front and back faces

DISPLACEMENT, U(3) x 10^{-7}/ ϵ

STRESS DISTRIBUTION, $\sigma^{11} \times 10^{-4}$
FRONT FACE

STRESS DISTRIBUTION, $\sigma^{11} \times 10^{-4}$

BACK FACE

STRESS DISTRIBUTION, $\sigma^{22} \times 10^{-4}$

FRONT FACE

STRESS DISTRIBUTION, $\sigma^{22} \times 10^{-4}$
BACK FACE

S-STEEL PROP 3135

DISPLACEMENT, U(3) × $10^4/\epsilon$

STRESS DISTRIBUTION, $\sigma^{11} \times 10^{-2}$
FRONT FACE

S-STEEL PROP 3133

STRESS DISTRIBUTION, $\sigma^{22} \times 10^{-2}$
FRONT FACE

STRESS DISTRIBUTION, $\sigma^1 \times 10^{-2}$

BACK FACE

S - STEEL PROP 3133

STRESS DISTRIBUTION, $\sigma^{zz} \times 10^{-2}$

BACK FACE

These extraneous values apparently did not effect the remaining 88 eigenvalues as examination of pages   to   will verify; they did indicate that the accumulated errors were becoming critical, and, as a matter of fact, a subsequent trial run using 96 degrees of freedom failed.

It is believed that the bulk of the accumulated round-off errors is generated in the process of forming and integrating the energy matrices. To alleviate this condition, it would be necessary to utilize double-precision arithmetic in this section of the program. This, however, would be a major programming effort and the increased cost of machine time could triple.

An 8 x 9 integrating quadrature mesh is used. Test runs made with 10 x 10 and 12 x 12 meshes exhibited no significant changes in the eigenvalues; thus, these expensive refinements do not contribute to any increase in accuracy.

For the great majority of blade configurations, it is believed that the present program will generate accurate estimates of the natural frequencies. This series of runs indicates that the natural frequencies have indeed "settled down" at 90 degrees of freedom, and that these figures can be referred to, with confidence. The mode shapes remained essentially unchanged between 75 and 90 degrees of freedom.

The limitation on size due to the accumulation of round-off error, represents a much more severe restriction on stress program than on the vibration program. The natural modes of vibration are an "integrated" property of the entire blade and thus are intrinsically more responsive to "settling down" as the size of the system grows. On the other hand, the stress program mesh furnish quantitatively precise data over the entire domain of the blade planform. To attain the same degree of accuracy for the stress distributions as is now obtained for the

vibration frequencies, it is necessary to add more Rayleigh functions, which leads to larger systems of equations.

The method now used to solve the system of linear equations, depends on this system being positive-definite. This condition is negated by the round-off error incurred in forming a large-size strain energy matrix; a technique to solve the system of equations which does not depend upon the property of positive definiteness must be employed in order to accommodate a size larger than say 84 by 84 . A Gaussian elimination process, followed by a Seidelian iteration to improve the solution vector should accomplish this result.

The cost of running the present stress program has been reduced from 1-1/2 hours to approximately 55 minutes. See Appendix II for details. This cost could be further reduced 25-30% by converting the equipment to an IBM 7094 with high-speed, high-density tape units.

REFERENCES

1. Lane, Frank, "A Shell Analysis of Propeller Blade Vibration,"
   Interim Scientific Report No. 1, April 1959.

2. Lieberman, Edward, "Propeller Blade Vibration Analysis," Final
   Report, GASL Technical Report No. 210, December 1960.

3. Lieberman, Edward, "Propeller Blade Static Stress Analysis,"
   GASL Technical Report No. 225, February 1961.

4. Slutsky, S. and Tamagno, J., "Propeller Blade Vibration Testing,"
   GASL Technical Report No. 213, December 1960.

The Rayleigh functions must be chosen to satisfy the displacement boundary conditions at the root, vis. $u_1 = u_2 = 0$ and $\dfrac{\partial u_3}{\partial y^I} = u_3 = 0$. The geometry of the root is approximated by a parabola of the form, $y^{(2)} = a y^{(1)^2} + by^{(1)} + c$. Since the root passes through the origin, the constant term, c, vanishes. The coefficients a, and b, are expressed in terms of the coordinates of the end-points of the root, which are given on input card 2.

The boundary conditions for u_1 and u_2 are satisfied by the functions, φ_i, those for u_3 by the functions ψ_i (i = 1, 2, ... 36). These functions are listed below.

$\varphi_1 = (y^{(1)} - ay^{(2)^2} - by^{(2)})$

$\varphi_2 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)}$

$\varphi_3 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(2)}$

$\varphi_4 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^2}$

$\varphi_5 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(2)^2}$

$\varphi_6 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^2} y^{(2)}$

$\varphi_7 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^2} y^{(2)}$

$\varphi_8 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^2} y^{(2)^2}$

$\varphi_9 = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)} y^{(2)^2}$

$\varphi_{10} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^3}$

$\varphi_{11} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(2)^3}$

$\varphi_{12} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(2)}$

$\varphi_{13} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)} y^{(2)^3}$

$\varphi_{14} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(1)^4}$

$\varphi_{15} = (y^{(1)} - ay^{(2)^2} - by^{(2)}) y^{(2)^4}$

$\psi_1 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2$

$\psi_2 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)}$

$\psi_3 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(2)}$

$\psi_4 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^2}$

$\psi_5 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(2)^2}$

$\psi_6 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)} y^{(2)}$

$\psi_7 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^2} y^{(2)}$

$\psi_8 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^2} y^{(2)^2}$

$\psi_9 = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)} y^{(2)^2}$

$\psi_{10} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^3}$

$\psi_{11} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(2)^3}$

$\psi_{12} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^3} y^{(2)}$

$\psi_{13} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)} y^{(2)^3}$

$\psi_{14} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(1)^4}$

$\psi_{15} = (y^{(1)} - ay^{(2)^2} - by^{(2)})^2 y^{(2)^4}$

$$\varphi_{16} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} \, 5$$

$$\varphi_{17} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(2)} \, 5$$

$$\varphi_{18} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)4} y^{(2)}$$

$$\varphi_{19} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} y^{(2)4}$$

$$\varphi_{20} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)3} y^{(2)2}$$

$$\varphi_{21} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)2} y^{(2)3}$$

$$\varphi_{22} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} \, 6$$

$$\varphi_{23} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(2)} \, 6$$

$$\varphi_{24} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)5} y^{(2)}$$

$$\varphi_{25} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} y^{(2)5}$$

$$\varphi_{26} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)4} y^{(2)2}$$

$$\varphi_{27} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)2} y^{(2)4}$$

$$\varphi_{28} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)3} y^{(2)3}$$

$$\varphi_{29} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} \, 7$$

$$\varphi_{30} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(2)} \, 7$$

$$\varphi_{31} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)6} y^{(2)}$$

$$\varphi_{32} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)} y^{(2)6}$$

$$\varphi_{33} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)5} y^{(2)2}$$

$$\varphi_{34} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)2} y^{(2)5}$$

$$\varphi_{35} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)4} y^{(2)3}$$

$$\varphi_{36} = (y^{(1)} - ay^{(2)})^2 - by^{(2)}) \, y^{(1)3} y^{(2)4}$$

$$\psi_{16} = (y^{(1)} - ay^{(2)})^2 - by^{(2)})^2 y^{(1)} \, 5$$

$$\psi_{17} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(2)} \, 5$$

$$\psi_{18} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)4} y^{(2)}$$

$$\psi_{19} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)} y^{(2)} 4$$

$$\psi_{20} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)3} y^{(2)2}$$

$$\psi_{21} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)2} y^{(2)3}$$

$$\psi_{22} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)} \, 6$$

$$\psi_{23} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(2)} \, 6$$

$$\psi_{24} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)5} y^{(2)}$$

$$\psi_{25} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)} y^{(2)5}$$

$$\psi_{26} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)4} y^{(2)2}$$

$$\psi_{27} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)2} y^{(2)} 4$$

$$\psi_{28} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)3} y^{(2)3}$$

$$\psi_{29} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)} \, 7$$

$$\psi_{30} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(2)} \, 7$$

$$\psi_{31} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)6} y^{(2)}$$

$$\psi_{32} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)} y^{(2)6}$$

$$\psi_{33} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)5} y^{(2)2}$$

$$\psi_{34} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)2} y^{(2)5}$$

$$\psi_{35} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)4} y^{(2)3}$$

$$\psi_{36} = (y^{(1)} - ay^{(2)2} - by^{(2)})^2 y^{(1)3} y^{(2)4}$$

APPENDIX II

A great variety of techniques have been developed and employed to solve large systems of simultaneous equations. The relative usefulness of each technique is intimately related to the size and character of the system in question.. At all times, the programmer must contend with the problem of propagated round-off errors and recognize the economic necessity of minimizing machine time, consistant with the desired accuracy.

In the course of solving the two-matrix eigenvalue problem it was necessary to factor the strain energy matrix using multiple-precision arithmetic which utilized two "words" for the fraction - a total of 71 bits compared with 25 bits used for single precision (plus sign). After attemping several other techniques to solve the system of equations in the stress program all of which proved to be unacceptable for one reason or another, it was decided to utilize the existing coding of the factoring technique to generate an approximate inverse, and then try to improve the solution by various means. Three techniques are used, in series; the improvement effected by one procedure, materially assists the convergence of the following one.

1. Series Expansion to Improve the Inverse

Given a matrix, A, and an approximate inverse $\tilde{A}^{-1} = A^{-1} + E$, then

$$A \tilde{A}^{-1} = A(A^{-1} + E) = I + C \qquad \text{where } C = AE$$

The matrix C may be calculated; E is the error in the approximate inverse.

Solving for E, $\quad E = A^{-1}C$

$$E + EC = E(I+C) = A^{-1}C + EC = (A^{-1} + E)C = \tilde{A}^{-1}C$$

$$E(I+C)(I-C) = E(I-C^2) = \tilde{A}^{-1}C(I-C)$$

Multiplying by $(I+C^2)$: $\quad E(I-C^4) = \tilde{A}^{-1}(C-C^2+C^3-C^4)$

In general, $E(I-C^n) = \tilde{A}^{-1}(C+C^2+C^3 - \ldots - C^n)$

Thus the error matrix, E, may be calculated, subject to a truncation error, $-EC^n$. If the matrix C is "sufficiently" small, the series expansion will converge, and the truncation error will be extremely small, compared to E. Then, since $A^{-1} = \tilde{A}^{-1} - E$, we may write

$$A^{-1} = \tilde{A}^{-1} - \tilde{A}^{-1} (C-C^2+C^3 - \ldots - C^n) \text{ or}$$

$$A^{-1} = \tilde{A}^{-1} (I-C+C^2-C^3 \ldots + C^n)$$

For this program, n = 8. If C is "too large", the series will diverge and the entire improvement of the solution will be done by the Seidelian iteration technique. Following this series expansion(if successful) is:

2. Iteration on Forcing Vector

Given the matrix A, a good approximation to its inverse, $\tilde{A}^{-1}$, and the forcing vector, p, in the system $Aq = p$. Then we may write

$$q_1 = \tilde{A}^{-1}p \text{ where } q_1 \text{ is the first approximation to the solution vector.}$$

To improve it, compute p_1; $Aq_1 = p_1$ or $A(q + \Delta q_1) = p + \Delta p_1$. Then we may solve for the error in the solution vector, $\Delta q_1 = \tilde{A}^{-1} \Delta p_1$ and writing $q_2 = q_1 + \Delta q_1$, can repeat the process. For this iteration to converge, the inverse, $\tilde{A}^{-1}$, must be "sufficiently" accurate. Otherwise, we must depend entirely upon the Seidelian iteration.

3. Seidel Iteration on the Solution Vector

Transposing the i^{th} equation of the system, we may solve for the i^{th} element of the solution vector in terms of the best values computed so far, for the other n - 1 elements of the solution vector:

$$q_i = \frac{1}{a_{ii}} \left[P_i - \sum_{\substack{j=1 \\ j \neq i}}^{n} a_{ij} q_j \right]$$

The program sweeps through the system many times until either a satisfactory tolerance is achieved or until the upper limit of iterations is attained. Since this iteration technique is unconditionally convergent for positive definite symmetric matrices, the final solution vector will have the necessary accuracy. The upper limit of the number of iterations depends upon the success attained by the previous two techniques. This upper limit is significantly reduced (thus saving machine time) if the prior iterations were successful to some extent.

Fig. 1
Blade Geometry and Coordinate Systems

Figure 2a

Figure 2b

DISTRIBUTION LIST

Copy No.

Copy No.

Officer-in-charge
Pasadena Annex
U.S. Naval Ordnance Test Station
Oceanic Research (Code P-508)
3202 E. Foothill Blvd.
Pasadena 8, Calif   27-29

Dr. G.B. Schubauer, Chief
Fluid Mechanics Section
National Bureau of Standards
Washington 25, D.C.   30

Dr. J.M. Franklin, Consultant
National Bureau of Standards
Washington 25, D.C. ·   31

Mr. I.E. Garrick - Director
Langley Research Center
Langley Field, Virginia   32

Mr. D.J. Marten - Director
Langley Research Center
Langley Field, Virginia   33

Natl Research Council of Can.
Hydromechanics Lab
Ottawa 2, Canada   34

Mr. R.P. Godwin, Acting Ch.
Office of Res. & Development
Maritime Administration
441 G. Street, N.W.
Washington 25, D.C.   35

Commander
Armed Svc Tech Inf Agency
Attention: TIPDR
Arlington Hall Station
Arlington 12, Virginia   36-45

Office of Technical Services
OTS, Dept of Commerce
Washington 25, D.C.   46

Commander
Air Res & Development Command
Attention: Mechanics Branch
AFOSR
14th and Constitution
Washington 25, D.C.   47

Commander
Wright Air Development Divn
Attn: Mr. W.Mykytow, Dyn Branch
Wright-Patterson AFB, Ohio   48

Dr. F.H. Todd
Superintendent, Ship Divn.
National Physical Lab.
Teddington, Middlesex, Eng.   49

Head Aerodynamics Division
National Physical Lab.
Teddington, Middlesex, Eng.   50

Mr. A. Silverleaf
National Physical Lab.
Teddington, Middlesex, Eng.   51

Head, Aerodynamics Dept.
Royal Aircraft Establishment
Mr. M.O.W. Wolfe
Farnborough, Hants, Eng.   52-53

Boeing Airplane Company
Seattle Division
Mr. M.J. Turner
Seattle, Washington   54

Dr. M.S. Plesset
Calif Institute of Technology
Pasadena, California   55

Dr. T.Y. Wu
Calif. Institute of Technology
Pasadena, California   56

Dr. A.J. Acosta
Calif. Institute of Technology
Pasadena, California   57

DISTRIBUTION LIST

Copy No.

Copy No.

Mr. A.D. MacLellan
Systems Dynamics Group
Convair
P.O. Box 1950
San Diego 12, California   58

Mr. H.T. Brooke
Hydrodynamics Group
Convair
P.O. Box 1950
San Diego 12, California   59

Mr. W. Targoff
Cornell Aeronautical Lab
4455 Genesee Street
Buffalo, New York   60

Mr. R. White
Cornell Aeronautical Lab
4455 Genesee Street
Buffalo, New York   61

Mr. C.J. Henry
Director, Davidson Lab
Stevens Institute of Technology
Hoboken, New Jersey   62-63

Mr. S. Tsakonas
Director, Davidson Lab
Stevens Institute of Technology
Hoboken, New Jersey   64

Electric Boat Division
General Dynamics Corp
Attn: Mr. Robert McCandliss
Groton, Connecticut   65

Gibbs and Cox, Inc.
21 West Street
New York, New York   66

Mr. E. Baird
Grumman Aircraft Engrg Corp
Bethpage, LI, New York   67

Mr. E. Bower
Grumman Aircraft Engrg Corp
Bethpage, LI, New York   68

Grumman Aircraft Engrg Corp
Dyn Developments Division
Babylon, New York   69

President, Hydronautics, Inc.
200 Monroe Street
Rockville, Maryland   70-71

Lockheed Aircraft Corp
Missiles & Space Divn
Attn: R.W. Kermeen
Palo Alto, California   72

Prof. H. Ashley
Mass Institute of Technology
Fluid Dyn Research Lab
Cambridge 39, Mass   73

Prof. M. Landahl
Mass Institute of Technology
Fluid Dyn Research Lab
Cambridge 39, Mass   74

Prof. J. Dugundji
Mass Institute of Technology
Fluid Dyn Research Lab
Cambridge 39, Mass   75

Midwest Research Institute
Attn: Mr. Zeydel
425 Volker Boulevard
Kansas City 10, Missouri   76

Ordnance Research Laboratory
Pennsylvania State University
Dr. M. Sevik
University Pk, Pennsylvania   77

DISTRIBUTION LIST

Copy No.

Copy No.

Dr. H.N. Abramson - Director
Dept of Mechanical Sciences
Southwest Research Institute
8500 Celebra Road
San Antonio 6, Texas   78

Mr. G. Ransleben - Director
Dept of Mechanical Sciences
Southwest Research Institute
8500 Celebra Road
San Antonio 6, Texas   79

Editor, Applied Mech Review
Dir - Dept of Mechanical Sci
Southwest Research Institute
8500 Celebra Road
San Antonio 6, Texas   80

Dr. B. Perry
Stanford University
Department of Mathematics
Stanford, California   81

Dr. E.Y. Hsu
Stanford University
Department of Mathematics
Stanford, California   82

State University of Iowa
Iowa Institute of Hydraulic Res
Prof. L. Landweber
Iowa City, Iowa   83

Technical Research Group, Inc
Attn: Dr. P. Kaplan
2 Aerial Way
Syosset, LI, New York   84-85

The Rand Corporation
Attn: Dr. B. Parkin
1700 Main Street
Santa Monica, Calif   86

University of California
Dept of Engrg
Institute of Engrg Res
Attn: Dr. J.V. Wehausen
Berkeley, California   87

Prof H.A. Schade, Head
Dept of Naval Architecture
University of California
Berkeley, California   88

Prof. B. Silberman
St. Anthony Falls Hydraulic Lab
University of Minnesota
Minneapolis, Minn   89

Mr. J.N. Wetzel
St. Anthony Falls Hydraulic Lab
University of Minnesota
Minneapolis, Minn.   90